


■ No. 2012-111    ■ Date: 2013/3/18

Model : KE430F, BE438F


Title : Be careful while connector insertion

We have received E401 for motor pcb.

Please note, the P1 connector will going insert even upside-down direction without any pay attention  
Therefore be careful and make sure current direction while P1 connector insert to the motor pcb



P1 connector



Connector upside-down



It will become crack