

## MFC-6800 Supported PC Software Functions

Computer Platform & Operating System		Software Functions	PC Interface
Windows®	95	Printing, PC Fax Send, Scanning	Parallel only
	98, 98SE	Printing, PC Fax Send, Scanning	Parallel/USB
	Me	Printing, PC Fax Send, Scanning	Parallel/USB
	NT® Workstation 4.0	Printing, PC Fax Send, Scanning	Parallel only
	2000 Professional	Printing, PC Fax Send, Scanning	Parallel/USB
	XP	Printing <sup>1</sup> , PC Fax Send <sup>3</sup> , Scanning <sup>1</sup>	Parallel/USB
Mac®	OS 8.5 - 8.51	Printing, PC Fax Send	USB <sup>4</sup> only
	OS 8.6 - 9.2	Printing, PC Fax Send, Scanning <sup>2</sup>	USB <sup>4</sup> only
	OS X v. 10/10.1	Printing only	USB <sup>4</sup> only

<sup>1</sup> Driver can be downloaded from <http://solutions.brother.com>.

<sup>2</sup> Dedicated "Scan to" key does not function with Apple® Operating Systems.

<sup>3</sup> Brother PC Fax is not supported. Please use Windows® XP built-in function.

<sup>4</sup> Third party USB ports are not supported.

Please use Windows® XP and Office XP built-in functions. (Windows® XP restricts scanning resolution to a maximum of 600x600 dpi.)

## MFC-6800 Minimum System Requirements

Computer Platform & Operating System		Processor Speed	Minimum RAM	Recommended RAM	Available Hard Disk Space
Windows®	95	Pentium 75MHz	32MB	32MB	50MB
	98, 98SE	Pentium 150MHz	32MB	32MB	50MB
	Me	Pentium 75MHz	32MB	64MB	50MB
	NT® Workstation 4.0	Pentium 133MHz	32MB	64MB	50MB
	2000 Professional	Pentium 75MHz	64MB	128MB	50MB
	XP	Pentium 133MHz	64MB	128MB	50MB
Mac®	OS 8.5 - 8.51	All base models meet minimum requirements			50MB
	OS 8.6 - 9.2				50MB
	OS X v. 10/10.1				50MB