

GT DIGITAL GARMENT PRINTERS


For Technical Assistance Please Call Toll Free 1-877-4BROTHER Email: tsupport@brother.com

Install the USB Cord

1. Locate the USB port on back of the machine




2. Plug into the machine end (firewire) port.



3. Plug into the computer end (USB) port.





4. Follow instruction on "new found hardware" on the computer screen.