


■ No. 2014-T003

■ Date: 2014/1

Model : BAS-311H, KE-430FX/430FS, BE-438F/FX

Title : Parts Book Correction(Thread Breakage Detector Set)

There was a wrong parts code in the parts book of BAS-311H as following.




*For Europe

■ No. 2014-T003


< 2/2 >

• BAS-311H



• KE-430F/FX/FS

• BE-438F/FX



*Please see the instruction manual of thread breakage detector set for detail.