	ng System	Software Functions	PC Interface				
Windows®	98, 98SE		USB 2.0 Full Speed				
	Me	Printing, PC Fax Send <sup>4</sup> , Scanning <sup>2</sup> ,					
	2000	Removable Disk <sup>5</sup>					
	Professional	Kelliovable Disk					
	ХР						
Mac <sup>®</sup> Operating Systems	OS 8.6	Printing, PC Fax Send <sup>4</sup>	USB 2.0				
	OS 9.x	Printing, PC Fax Send <sup>4</sup> , Scanning <sup>3</sup> ,					
		Removable Disk <sup>5</sup>					
	OS X v. 10.2.4	0.2.4 Printing, PC Fax Send <sup>4</sup> , Scanning,					
	or greater	Removable Disk <sup>5</sup>					
USB is not supported under Windows $^{ extsf{8}}$ 95 or Windows NT 4.0 $^{ extsf{8}}$							
To download the latest drivers, access www.brother.com							
1. Microsoft <sup>®</sup> Internet Explorer 5 or greater.							
2. Maximum 1200 x1200 dpi scanning resolution with Windows <sup>®</sup> XP (resolutions up to 19,200 x 19,200dpi can be selected using the Brother Scanner Utility).							

PC Fax supports black and white faxing only.
Removable disk is a function of the PhotoCapture Center <sup>®</sup> feature.

## MFC-3240c Minimum System Requirements

Computer Platform & Operating System		Processor Speed	Minimum RAM	Recommended RAM	Hard Disk Space (For Drivers)
Windows®	98, 98SE	Pentium <sup>®</sup> II or equivalent	32MB	64MB	90MB
	Me		32MB	64MB	90MB
	2000 Professional		64MB	128MB	90MB
	ХР		128MB	256MB	150MB
Mac <sup>®</sup> Operating Systems	OS 8.6 - 9.2	All base models meet minimum requirements			50MB
	OS 8.6 - 9.2	All base models meet minimum requirements		64MB	80MB
	OS X v. 10.1/ 10.2.1- 10.3 or greater	All base models meet minimum requirements	128MB	160MB	80MB