

## MFC-3420C Supported PC Software Functions

Computer Platform & Operating System		Software Functions	PC Interface
Windows®	98, 98SE	Printing, PC Fax Send, Scanning	USB
	Me	Printing, PC Fax Send, Scanning	USB
	NT® Workstation 4.0	Printing, PC Fax Send, Scanning	USB
	2000 Professional	Printing, PC Fax Send, Scanning	USB
	XP	Printing, PC Fax Send, Scanning <sup>2</sup>	USB
Mac® Operating Systems	OS 8.6 - 9.2	Printing, PC Fax Send, Scanning <sup>3</sup>	USB <sup>5</sup>
	OS X v. 10/10.1	Printing, PC Fax Send, Scanning <sup>3,4</sup>	USB <sup>5</sup>

Windows® 95 or Windows NT® 4.0 do not support USB.

For the latest drivers, access the Brother Solutions Center at <http://solutions.brother.com>. All software supplied only on CD.

\* : Based on Brother #1 chart with MMR Coding System and Standard Resolution

9: Up to 4800x1200 optimized dpi color output achievable using Photo mode when printing on high quality photo paper. (See User's Guide for details.)

1: Standard Resolution

2: Maximum Scanning resolution with Windows® XP is limited to 1200 x1200 dpi (resolutions up to 9600 dpi can be selected using the Brother Scanner Utility).

3: Dedicated "Scan" key does not function in the Mac® Operating Systems.

4: Scanning only available for Mac® OS 10.2.1 or greater.

5: Third party USB ports are not supported.

## MFC-3420C Minimum System Requirements

Computer Platform & Operating System		Processor Speed	Minimum RAM	Recommended RAM	Available Hard Disk Space
Windows®	98, 98SE	Pentium 75MHz	24MB	32MB	80MB
	Me	Pentium 150MHz	32MB	64MB	80MB
	2000 Professional	Pentium 133MHz	64MB	128MB	80MB
	XP	Pentium 233MHz	64MB	128MB	80MB
Mac® Operating Systems	OS 8.6 - 9.2	All base models meet minimum requirements	32MB	64MB	80MB
	OS X v. 10/10.2.0 or greater	All base models meet minimum requirements	128MB	160MB	80MB