

MFC-4820C Supported PC Software Functions

Computer Platform & Operating System		Software Functions	PC Interface
Windows®	98, 98SE	Printing, PC Fax Send, Scanning	USB
	Me	Printing, PC Fax Send, Scanning	USB
	2000 Professional	Printing, PC Fax Send, Scanning	USB
	XP	Printing, PC Fax Send, Scanning ¹	USB
Mac® Operating Systems	OS 8.6 - 9.2	Printing, PC Fax Send, Scanning ²	USB ⁴
	OS X v. 10/10.1 or greater	Printing, PC Fax Send, Scanning ^{2,3}	USB ⁴

USB is not supported under Windows 95® or Windows NT 4.0®.

For the latest drivers, access the Brother Solutions Center at <http://solutions.brother.com>. ♦ All software supplied only on CD.

1. Maximum Scanning resolution with Windows® XP is limited to 1200x1200 dpi (resolutions up to 9600x9600 dpi can be selected using the Brother Scanner Utility).

2. Dedicated "Scan to" key does not function in the Mac® Operating Systems.

3. Scanning only available for Mac® OS 10.2.1 or greater.

4. Third party USB ports are not supported.

MFC-4820C Minimum System Requirements

Computer Platform & Operating System		Processor Speed	Minimum RAM	Recommended RAM	Available Hard Disk Space
Windows®	98, 98SE	Pentium 75MHz	24MB	32MB	150MB
	Me	Pentium 150MHz	32MB	64MB	150MB
	2000 Professional	Pentium 133MHz	64MB	128MB	150MB
	XP	Pentium 233MHz	64MB	128MB	280MB
Mac® Operating Systems	OS 8.6 - 9.2	All base models meet minimum requirements			50MB
	OS X v. 10/10.1 or greater	All base models meet minimum requirements	128MB	160MB	50MB