

RECOMMENDABLE SPARE PARTS LIST FOR BAS-311F

NAME	P/NO.	Q'TY
SET SCREW, SM3.57	144458001	1
SCREW PAN SM4.37-40x5	062680512	2
CROSS ROLLER	S42778000	2
LINEAR BUSH	S35183000	2
Y-TIMMING BELT	S10077100	1
LINEAR GUIDE SET, 311	S59741000	2
X-TIMMINGBELT, A311	S42790000	1
X-TIMMINGBELT, B311	S42793000	1
SCREW	S10352101	2
PRESSER FOOT A	S42843001	1
SCREW, SM3.57x12	S13399001	1
SHUTTLE RACE THREAD GUIDE	S02429101	1
DRIVER HR	S55215001	1
BOBBIN CASE ASSY, B	152686101	1
TENSION SPRING B	144588001	1
SCREW, BOBBIN CASE SPRING	S16492101	1
BOBBIN TENSION SPRING	S15667001	1
BOBBIN, LA	S15665001	4
RIBBER RING	120448051	1
KNIFE	157968001	1
MOVABLE KNIFE ASSY	S10205001	1
WASHER, MOVABLE KNIFE(T=0.4)	S10208001	1
WASHER, MOVABLE KNIFE(T=0.5)	S10208002	1
WASHER, MOVABLE KNIFE(T=0.6)	S10208003	1
MOVABLE KNIFE COLLAR	S00705001	1
SCREW , SM4.37	S10209101	1
FIXED KNIFE	S10210201	1
SCREW, SM2.38	111140002	2
SCREW, FLAT SM4.37	100032004	2
NEEDLE HOLE PLATE, F	S10213001	1
WIPER	S10470101	1
SCREW , BIND SM4.37-40x5	060680512	1
WIRE ASSY WORK CLAMP LIFTER	S42868001	1
SENSOR HARNESS ASSY H/P	S56166000	1
SYNCRONIZER ASSY	S48666001	1

MAIN PCB ASSY	S53884001	2
FUSE, 5A FB	S08030000	2
FUSE, 6A	153242000	2
3.5 MEDIA 2HD	S43273000	1
POWER SUPPLY PCB ASSY	S49939001	1
PANEL PCB ASSY	S56151000	1
FDD 3.5	S43224000	1
2 PEDAL FOOT SW HARNESS ASSY , 3	S42259000	1
FUSE 7A : FB	S48580000	3
SOLENOID VALVE	S43683001	1